

Security Cable Installation Instructions



Step 1 Remove the screw from the face plate.



Step 2

Place the small end of the cable (choker hole) in between the face plate and the screw. (Secure the screw tightly in the opening, as seen in the picture).



Step 3

On the larger end (loop), place the loop between the flowmeter and the adapter. (Tighten the flowmeter to the adapter, as seen in the picture).



Step 4 Attach flowmeter to the wall.

GR-MAN-MEDSCII V1